



PARTS Bulletin

URGENT: Please distribute copies for the following people within your organization:

Owner ☒ Sales ☒ Customer Service ☒ Service Techs ☒

Parts Bulletin #3 May 2016

To: All VSGA Distributors

Subject: New Switch for SPOA10

Ladies and Gentlemen,

In order to improve the user experience of our 2 post lift main switch, Rotary has designed new switch for SPOA10.

For the lifts produced since March 2016, the new switch has been applied and packed along with entire lift.


For the lifts before March 2016, if the customer wants to replace to new switch, the lift will need extra components including new switch kit and additional wires. A correct serial number is necessary for checking the height where new switch can be placed and send right length wires.

SPOA10 new switch kit (Long code: 52.01.02.05. FA9147 kit) contains parts as below:

PART NO.	DISCRIPTION	QTY
FA9147	FA9147 3Ø Control Box	1
FA9153-1	Mounting Bracket	1
40375	5/16"-18NC x 1/2" SOC FH C'SUNK SCREW	1
40780	1/4" Flat Washer	4
40779	1/4" Star Washer	4
40062	1/4"-20NC x 1/2" HHCS	4
40217	5/16" Flat Washer	2
40401	5/16"-18NC x 1/2" HHCS	2

An additional 3.3m 2 cores wire will also be included in the package for connecting the proximity switch and new control box.

New added parts can be seen in the following figure:



(Detail Installation information please check technical file: Replacement Instruction on New Switch of SPOA10.)

Sincerely,

Luyao Huang
Technical Support Engineer
2016/6/3