



PRODUCT BULLETIN

URGENT: Please distribute copies to the following people within your organization:

☒ Owner ☒ Sales ☒ Customer Service ☒ Service Techs

Subject: Manual Pump Update

Dear valued distributor,

We are pleased to announce the release of the new rolling jack manual pump. After meeting our stringent quality and durability testing, the new pump has been available since April 2021.

Please review below for visual comparison:



Old pump SP06-9100G



New pump LY06-9100G

Please note the new pump has been implemented as running change and is a direct replacement for the original pump.

The following rolling jacks with manual pumps are impacted, RJ45, NRJ45, RJ35. The rolling jack assembly model number remain the same.


The maximum pressure for the pump is set at the factory and under normal operation does

not require adjustment. For testing and troubleshooting the rolling jack pressure can be checked as follows. A pressure gauge can be connected to the oil outlet of the pump for testing and inspection.

The tools and operation details required for pressure adjustment are shown below:



PIC.1



PIC.2



PIC.3



PIC.4

The bleed screw is on the side of the pump.



For any enquiries relating to this announcement, please contact our customer support at huihua.lu@rotaryliftdasia.com or cmiller@vsgdover.com

Regards,

VSGA Customer Service
2021-5-11