

# PARTS BULLETIN

**URGENT:** Please distribute copies for the following people within your organization:

☒ Owner   ☒ Sales   ☒ Customer Service   ☒ Service Techs

**Subject: Change of DL9 Power Unit**

Dear valued distributor,

Please be noted that the Direct Lift DL9 will be manufactured and supplied with a revised power unit for Australia and New Zealand market from July 14<sup>th</sup>, 2018.

Therefore, the lift model numbers will change from DL9E(V)1\*\*\*\* to DL9E(V)2\*\*\*\*.

Please see details as below.

|   | Old Power Unit           | New Power Unit                               |
|---|--------------------------|--|
| <b>Part No</b>  | P3610 (1φ)<br>P3046 (3φ) | PDL1331 (1φ)<br>PDL1333 (1φ)<br>PDL4421 (3φ) |
| <b>Specifications</b>   | 1φ,50/60Hz,230V          | 1φ,50/60Hz,230V                              |
|   | 3φ,50/60Hz,230/460V      | 3φ,50Hz,380V                                 |
| <b>Lift Model No</b>  | DL9E(V)1****             | DL9E(V)2****                                 |
| Can be interchanged<br>(PDL1333 combined with control box FA9147Y-UL-14 to replace PDL3610) |                          |  |

Please find pictures below to help visually identify the correct power units in the field.



Please be noted that the change of power units will not affect the specifications or performance of the lift.

For any questions concerning this announcement, please direct to our customer support at [huihua.lu@rotaryliftdasia.com](mailto:huihua.lu@rotaryliftdasia.com).

Regards,

VSGA Customer Service  
2018/07/10